



# PLUMBING REPORTS \$55 INC GST

Water leaks cost  
money -

Plumbing Report

- + Check Flexilines to ensure they are not rusted/damaged
- + Check all taps to ensure no leaks
- + Check toilets for leaks and signs of failure issues
- + Check under sinks/ vanities to ensure no leaks on wastes
- + Check hot water temperature .  
Water needs to be no hotter than 50 degrees

Quote will be given if any issues are discovered. Should you wish to proceed with work, a booking will be made at a later date. If a roof inspection is also required, charge will be an additional \$33 inc gst.